

XIP-3901-FS

Release History

| Release Version | Comprising: | | Release Date | User Manual for this Release (Grass Valley Document #) |
|-----------------------|------------------|------------------|--------------|--|
| | Firmware Version | Software Version | | |
| 2.0.0 | 2.0.0.130 | 2.0.0 | 2020-01-13 | 13-03065-010 Rev. AF |
| 1.1.0 | 1.1.0.91 | 1.1.0 | 2019-02-15 | 13-03065-010 Rev. AD |
| 1.0.0 | 1.0.0.82 | 1.0.0 | 2018-11-07 | 13-03065-010 Rev. AC |

WARNINGS

| | |
|-------------------------------|--|
| XIP3901FS-766 | <p>Upgrade/Downgrade between 2.x.x and 1.x.x</p> <p>Each version has its settings. Consequently upgrading or downgrading between 2.x.x and 1.x.x might require ETH3 reconfiguration</p> |
|-------------------------------|--|

NOTES: The iControl compatibilities shown below are officially supported by Grass Valley. Earlier versions may also work, with bugs or limited features.

The reference number (Ref #) given for each feature or bug in these release notes refers to internal Grass Valley documentation.

UPGRADE PACKAGE: 2.0.0

Firmware version: [2.0.0 \(CPU 2.0.0.130, FPGA 2.0.0.15\)](#)

Release date: [2020-01-13](#)

iControl compatibility: [7.51+](#)

iControl Solo compatibility: [7.51+](#)

RCP-200 compatibility: [N/A](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

Release type: [Official release](#)

ENHANCEMENTS & NEW FEATURES

| Ref # | Description |
|-------------------------------|--|
| XIP3901FS-695 | <p>Additional HDR processing</p> <p>Here are the new features :</p> <ol style="list-style-type: none"> 1. Support of BBC LUTs 2. Support of Custom LUTs 3. Possibility to force a new VPID <p>These new feature required XIP-3901-UDC-HDR option</p> |
| XIP3901FS-697 | <p>Additional Video Test Pattern</p> <p>Possibility to enable HLG and PQ Test pattern on 3G, 12G and Quad Link 3G SDI outputs</p> |
| XIP3901FS-764 | <p>Additional Network features</p> <p>Here are the new features:</p> <ol style="list-style-type: none"> 1. Support new bridged interface through the frame controller's Ethernet ports. This must not contain any of the frame controller's IP addresses 2. Support DHCP 3. Support LLDP |

| | |
|-------------------------------|---|
| XIP3901FS-763 | <p>Additional settings and statuses on the local menu</p> <p>Here are the new features:</p> <ol style="list-style-type: none"> 1. Possibility to set ETH3 and FRM interface through local menu 2. Possibility to display ETH3 and FRM interface statuses |
| XIP3901FS-640 | <p>Audio Pass-through on Quad Link 3G</p> <p>On Quad Link 3G and Quad Link 3G - 2SI/Square mode, Audio should pass-through on 3G Link 1 to 3G Link 4</p> |
| | |

BUG FIXES

| Ref # | Description |
|-------------------------------|---|
| XIP3901FS-612 | <p>Colorimetry info on VPID doesn't follow on test pattern</p> <p>When Test Pattern is enabled outgoing colorimetry follows the SDI input colorimetry when it should be SDR BT.709</p> |

KNOWN BUGS & LIMITATIONS

| Ref # | Description |
|-------------------------------|--|
| XIP3901FS-769 | <p>Custom LUT Limitations</p> <p>Custom LUTs are not managed by Factory, User Presets and Profiles. To delete Custom LUTs, you need to manually delete each of them.</p> <p>Furthermore, Custom LUTs Files are shared by all XIP-3901 applications: XIP-3901-UC, XIP-3901-DC, XIP-3901-FS, and so on.</p> |

| | |
|-------------------------------|---|
| XIP3901FS-750 | <p>Metadata doesn't pass-through on 3G Link 2 to 3G Link 4</p> <p>On Quad Link 3G and Quad Link 3G - 2SI/Square mode, Metadata doesn't pass-through on 3G Link 2 to 3G Link 4</p> |
| XIP3901FS-709 | <p>On minimum Delay, Audio doesn't pass-through on 3G Link 2 to 3G Link 4</p> <p>On Quad Link 3G and when Minimum delay is enabled, Audio doesn't pass-through on 3G Link 2 to 3G Link 4</p> |
| XIP3901FS-542 | <p>No error is reported for 3G Level B DS sources.</p> <p>3G Level B Dual Stream input signals are not supported. They are erroneously identified as Dual Link. When this occurs, the error is not reported, but the output is invalid.</p> |
| XIP3901FS-543 | <p>Potential problem with metadata packet placement during 3 G-A to 3G-B operations.</p> <p><u>3G-A/Quad-Link 3G-A to 3G-B/Quad-Link 3G-B:</u></p> <p>Some incoming metadata packets, other than audio or any processed metadata, may pass through to the output and may end up on an incorrect line on link A and/or be placed on link B.</p> <p>This will occur only for 3G-A/Quad Link 3G-A inputs.</p> <p><u>3G-B/Quad-Link 3G-B to 3G-A/Quad-Link 3G-A:</u></p> <p>Some incoming metadata packets, other than audio or any processed metadata, may pass through to the output and may end up on an incorrect line.</p> <p>This will occur only for 3G-A/Quad-Link 3G-A outputs.</p> |
| XIP3901FS-544 | <p>SD-SDI video format is not reported.</p> <p>Although SD-SDI input signals are unsupported, the video format should be reported but is identified as "unknown format" instead.</p> |
| XIP3901FS-545 | <p>Application version is not updated in the local menu.</p> |

| | |
|--|---|
| | <p>Upgrading an application that is not in use won't update its application version in the local menu. The version in the local menu is updated at boot time.</p> |
|--|---|

UPGRADE PACKAGE: 1.1.0

Firmware version: [1.1.0 \(CPU 1.1.0.91, FPGA 1.0.0.30\)](#)

Release date: [2019-02-15](#)

iControl compatibility: [7.51+](#)

iControl Solo compatibility: [7.51+](#)

RCP-200 compatibility: [N/A](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

Release type: [Official release](#)

ENHANCEMENTS & NEW FEATURES

| Ref # | Description |
|-------------------------------|---|
| XIP3901FS-618 | <p>Wide HDR Ref White Range</p> <p>Support wide HDR Ref White range for :</p> <ul style="list-style-type: none"> - SDR to HLG BT.2100 - HLG BT.2100 to SDR - SDR to PQ BT.2100 - PQ BT.2100 to SDR |
| XIP3901FS-617 | <p>Input & Output Range</p> <p>Control Input Range for PQ BT.2100 to SDR and Output Range for SDR to PQ BT.2100</p> |

BUG FIXES

| Ref # | Description |
|-------------------------------|--|
| XIP3901FS-651 | <p>Card presets are not recovered on a profile.</p> <p>Card presets are not recovered when restoring profile.</p> |

KNOWN BUGS & LIMITATIONS

| Ref # | Description |
|-------------------------------|---|
| XIP3901FS-542 | <p>No error is reported for 3G Level B DS sources.</p> <p>3G Level B Dual Stream input signals are not supported. They are erroneously identified as Dual Link. When this occurs, the error is not reported, but the output is invalid.</p> |
| XIP3901FS-543 | <p>Potential problem with metadata packet placement during 3 G-A to 3G-B operations.</p> <p><u>3G-A/Quad-Link 3G-A to 3G-B/Quad-Link 3G-B:</u></p> <p>Some incoming metadata packets, other than audio or any processed metadata, may pass through to the output and may end up on an incorrect line on link A and/or be placed on link B.</p> <p>This will occur only for 3G-A/Quad Link 3G-A inputs.</p> <p><u>3G-B/Quad-Link 3G-B to 3G-A/Quad-Link 3G-A:</u></p> <p>Some incoming metadata packets, other than audio or any processed metadata, may pass through to the output and may end up on an incorrect line.</p> <p>This will occur only for 3G-A/Quad-Link 3G-A outputs.</p> |
| XIP3901FS-544 | <p>SD-SDI video format is not reported.</p> <p>Although SD-SDI input signals are unsupported, the video format should be reported but is identified as "unknown format" instead.</p> |
| XIP3901FS-545 | <p>Application version is not updated in the local menu.</p> <p>Upgrading an application that is not in use won't update its application version in the local menu. The version in the local menu is updated at boot time.</p> |

UPGRADE PACKAGE: 1.0.0

Firmware version: [1.0.0 \(CPU 1.0.0.82, FPGA 1.0.0.30\)](#)

Release date: [2018-11-07](#)

iControl compatibility: [7.51+](#)

iControl Solo compatibility: [7.51+](#)

RCP-200 compatibility: [N/A](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

Release type: [Official release](#)

KNOWN BUGS & LIMITATIONS

| Ref # | Description |
|-------------------------------|---|
| XIP3901FS-542 | <p>No error is reported for 3G Level B DS sources.</p> <p>3G Level B Dual Stream input signals are not supported. They are erroneously identified as Dual Link. When this occurs, the error is not reported, but the output is invalid.</p> |
| XIP3901FS-543 | <p>Potential problem with metadata packet placement during 3 G-A to 3G-B operations.</p> <p><u>3G-A/Quad-Link 3G-A to 3G-B/Quad-Link 3G-B:</u></p> <p>Some incoming metadata packets, other than audio or any processed metadata, may pass through to the output and may end up on an incorrect line on link A and/or be placed on link B.</p> <p>This will occur only for 3G-A/Quad Link 3G-A inputs.</p> <p><u>3G-B/Quad-Link 3G-B to 3G-A/Quad-Link 3G-A:</u></p> <p>Some incoming metadata packets, other than audio or any processed metadata, may pass through to the output and may end up on an incorrect line.</p> <p>This will occur only for 3G-A/Quad-Link 3G-A outputs.</p> |
| XIP3901FS-544 | <p>SD-SDI video format is not reported.</p> |

| | |
|-------------------------------|---|
| | <p>Although SD-SDI input signals are unsupported, the video format should be reported but is identified as "unknown format" instead.</p> |
| XIP3901FS-545 | <p>Application version is not updated in the local menu.</p> <p>Upgrading an application that is not in use won't update its application version in the local menu. The version in the local menu is updated at boot time.</p> |