

Zodiak

DIGITAL PRODUCTION SWITCHER

Release Notes Addendum

SOFTWARE VERSION 6.0.2

071812824
FEBRUARY 2006

the most watched worldwide

Contacting Grass Valley

Region	Voice	Fax	Address	Web Site
North America	(800) 547-8949 Support: 530-478-4148	Sales: (530) 478-3347 Support: (530) 478-3181	Grass Valley P.O. Box 599000 Nevada City, CA 95959-7900 USA	www.thomsongrassvalley.com
Pacific Operations	+852-2585-6688 Support: 852-2585-6579	+852-2802-2996		
U.K., Asia, Middle East	+44 1753 218 777	+44 1753 218 757		
France	+33 1 45 29 73 00			
Germany, Europe	+49 6150 104 782	+49 6150 104 223		

Copyright © Grass Valley. All rights reserved.

Grass Valley Web Site

The www.thomsongrassvalley.com web site offers the following:

Online User Documentation — Current versions of product catalogs, brochures, data sheets, ordering guides, planning guides, manuals, and release notes in .pdf format can be downloaded.

FAQ Database — Solutions to problems and troubleshooting efforts can be found by searching our Frequently Asked Questions (FAQ) database.

Software Downloads — Software updates, drivers, and patches can be downloaded.

Zodiak Release Notes Addendum

Note The Zodiak 6.0.2 software is being released in conjunction with the Kalypso 12.0.2 software, and does not contain new features or corrected issues.

Note The Zodiak manual set has been updated to cover version 6.0 software functionality. Documentation is available for download at the Grass Valley web site.

The information below is identical to the 6.0.1 Release Notes Addendum.

Software Issues Resolved in Release 6.0.1

Table 1. Resolved Software Issues

Area	Problem	ID
Bus Linking	Can't break link on ME 3 key busses when in a link relationship is enabled.	63641
E-MEM	Using Cut removes the next KF.	62784
Machine Control	More than 255 characters in M Series directory names will cause Kalypso to crash.	63095
Macros	Macros created with software versions earlier than 6.0.0 that loaded Still Store images fail to load these images when run with version 6.0.0.	63788

Software Issues Resolved in Release 6.0.0

Table 2. Resolved Software Issues

Area	Problem	ID
E-MEM	When performing a E-MEM register operation on the Register Operations menu, the PUT button is available but only highlights every other time when it should. Workaround: Ignore the tally state; the button performs normally when pressed.	23610
E-MEM Timeline Menu	On the E-MEM Timeline menu, the Enable level buttons do not delegate the same levels that you enable. The main control panel Enable Buttons do enable the delegations. Workaround: On the E-MEM Timeline menu, always delegate each level after you enable the level or use the Enable Buttons on the main control panel.	25450
Macros	Clearing NV Memory does not clear Macros.	50589
Menu	With the last router source selected in the R-MEM/Router Select screen, going to the Eng Setup/Source Definition screen and changing that source from Router to Direct, and then returning to the R-MEM/Router Select screen crashes the Menu application.	54571
NetCentral	Successful installation message is displayed immediately following an error message while trying to install the new NetCentral III Kalypso/Zodiak Provider.	39702
Still Store	Intermittently unable to perform a Still Store load more than once.	57300
Timelines	Timeline events for controlled external devices are ignored if keyframe duration < 1 frame. Workaround: For Timeline events that are used to control external devices, the minimum key frame duration between the events must be 1 frame or longer. The operator should change their E-MEMs so that the key frames for events that control external devices are at least 1 frame apart.	41599

Known Software Problems

Table 3. Known Software Problems

Area	Problem	ID
Chroma Key	When Source Memory is on, if a keyer specifying a Chroma Key is selected, but a Chroma Keyer is not available for use, Source Memory for that source reverts to Fixed Linear Key. Later, if a Chroma Keyer becomes available, selecting that keyer source produces a Fixed Linear Key, not the desired Chroma Key.	31404
Editor Interface	When using the 560 Mhz frame processor, whenever a command is sent to Zodiak from the edit controller there is a flash on the program output. When in Edit or Preview mode from the editor the transform engines will flash until edit is locked, then the problem will clear itself. So the problem will not be a part of the edit but will only be seen during the pre-roll and post roll. This problem is not seen with the 1 Ghz frame CPU.	40612
E-MEM	When using Auto-Run to run a timeline with the Reverse button enabled, E-MEM will cut to the first keyframe of the effect, then pop to the end of the effect and begin running backwards instead of just popping to the end of the effect and running backwards.	17398
E-MEM	When running an effect in reverse with several pauses in the timeline, the effect will stop at the first pause and will not continue running in reverse on subsequent button presses.	19095
E-MEM	Playing back an E-MEM timeline and jogging through the effect can sometimes produce different results. Workaround: Instead of using the jog knob to preview an effect, use the E-MEM run command to see how the effect looks.	23221
E-MEM	If an effect is learned to re-enter M/E 1 into M/E 2 or 3, then another effect is learned to re-enter M/E 2 or 3 into M/E 1 in a different register, the re-entries do not swap as they should.	23395

Table 3. Known Software Problems - (continued)

Area	Problem	ID
E-MEM	When Master E-MEM has multiple levels out of sync (for example, enabling one Master E-MEM level, partially running it, disabling that level and enabling another level, and then running it), and the Master E-MEM is parked at or past the end of the effect, pressing the Run button snaps all levels to the Master's current time and then the run stops because the effect is at the end. A second press of the Run button is then required to run the effect. A work around is to rewind effects manually before running them. (If the levels are already parked at their beginning, the rewind won't disturb that state.)	29836
E-MEM	Numeric "ENTER" is treated as a relative modification for E-MEM mod operations.	39273
E-MEM	In 300 Mode, the offset register indicator '^'b does not always display on the E-MEM RT Panel display when it should. The timeline display correctly shows the offset register condition.	51108
E-MEM	Recall/auto-run of effect sometimes does not run.	52161
File Operations	Cancelling a load user profile operation does not revert to a pre-load state.	60696
Freeze Fill	When key mode changes during source change, the keyer stays in freeze mode.	17424
GPI Output	If a negative value is entered for GPI output Duration, it wraps to max value. This is a problem with all UINT32 parameters from the keypad popup.	26248
Keyer	Using Utility 1 for Keyer Preset Pattern Border Utility Fill shows Utility 2 and vice versa.	58674
Keypad	Existing keypad values are not cleared when negative values are entered on the Main panel unless the negative key is pressed last. For example, if 5 is the starting value, pressing - 1 results in a -15 value. Pressing 1 - gives the desired -1 value.	29886
M/E	If a keyer is being processed through a Transform Engine on an M/E, selecting a re-entry source on PGM can cause a one field color shift of the keyed signal on PGM. The same color shift also appears on PST.	51775
Macros	Macros created to load Still Store images that were recorded into any directory other than the Default Still Store directory may not load these Still Store images after system reboot. Work around is to use Kalypso 6.0.1 software and use only the Default Still Store directory.	63031
Net Central	On failure of one or more fans in the frame, Net Central III reports an informational message that the system cooling-fans resumed normal operation. Clicking on the fan button in Net Central will correctly show which fans are operational and which fans are not. Whenever this fan message appears in the message window, the fan button should be checked to ensure all fans are operational.	35757
Re-Entry	At times, re-entry sources shift one line compared to direct sources.	53678
Router Interface	Router sources do not show up on Menu or panel if router source is via a Tie line.	60080
Shot Box	Resetting the Shot Box causes Master E-MEM to recall register 00. Work round is to make sure all levels are disabled on Master E-MEM before resetting the Shot Box.	50938
Still Store	Video Dropouts on still store image load.	12137
Still Store	Playing back a Still Store animation clip on multiple outputs causes the dropping of frames across all outputs. Playback will appear to be double speed or faster. There is no workaround for this problem, except to not load clips onto more than one output.	21148
Still Store	Still Store directory changes are not saved/recalled via E-MEM.	57570
Still Store	Loading a still into one output can unload another output.	61966
Still Store	After turning off a Video Key pair, loading a still into the channel that was Key unloads the still in the channel that was Fill.	62307
Still Store	Glitches can appear in still or playing animation if the Still Store is simultaneously doing a save or load operation.	29993 34672
Transform Engine	Pixelator appears masked and only operational on Keyers 1 and 3. Workaround: Only use Pixelator on Keyers 1 and 3.	50884

Table 3. Known Software Problems - (continued)

Area	Problem	ID
Transform Engine	Timing shift on screen when selecting a re-entry with aTE Key that has Fill Freeze enabled.	53960
Transform Engine	When a key signal is passed through a Transform Engine the filtering applied is incorrect at certain angles and sizes, which creates blurry video.	54858
Transform Engine	If the Pixelator is turned on for a PST PTN key with a border, the key background fills with the border color instead of being pixelated.	55789
Wipe	Wipe scaling problem. Wipes appear on screen after the transition has started and complete before the transition panel has finished its transition.	11641
Wipe	E-MEM effects from releases before V3.0 that use a box generator as a preset pattern source may not preserve the same box size. They will need to be recalled and the size of the preset pattern box generator adjusted before they will work properly.	35225