

Software Evaluation Release

Software: Imagestore V1.21
Products Affected: Imagestore IS2 running V1.xx

This software cannot be used to upgrade Imagestore IS2 V2.xx

Main Features since V1.17:

- Easysound new audio model
- Easysound GPI I/O now available when new audio model enabled
- “R3” automation command allows filename inquire
- Automation “fade to position” commands now can be deferred (For Presmaster V-fade)
- “Front Panel Mirror” now handles key press & release.
- “LOADLIVE.OXW” selected when “Load Live” taken to air (if present)
- 48KHz 16-bit WAV file support for Easyplay
- System Aspect ratio (4x3, 16x9) now available as global option (was Bugclock-specific)
- “Strict” and “Relaxed” automation modes for STX problems with certain automation systems.
- Includes finger server (not externally visible)
- Improved image load speed over 1.17 (big buffer)
- Corrections to output AES channel status
- Enhanced bugclock features:
 - Separate Time/Date formats and positions.
 - Improved handling of analog clocks with large faces.
- Support for In-Loop-Out and Ping-Pong Animations
- ‘Window Image’ support (Stored Key, Live Fill) but not yet in Animation builder
- Ethernet-based automation
- Independent Easyplay control from GPIs and automation
- Animation start/stop control from GPIs and automation
- Creates local thumbnails for MDS to speed operation
- logging of all FTB operations in system log file
- GPI features for Bugclock control added
- ‘Set Inputs’ (colour field/SDI) now moved to ‘Setup’ menu tree.
- On-screen display can show GPI/fader values.
- RCP-200 ‘home page’ status info improved.
- Automation baud rates can be increased to 57600

Compatibility issues

Tone Generator not present in New Audio Model
Unsolicited packets sent by Imagestore.

Major Bugs Fixed:

Easyplay handling of load live
Incorrect STX handling on Automation ports now fixed
“Playlist full” message when adding to playlist
Playlists handle filenames with spaces
Playlist number on polyphoto shown incorrectly