

HDA-1941 – Upgrade Package 1.0.2

Upgrade Package Release History

Release Version	Comprising:		Release Date	Version Details	User Manual for this release (Miranda document #)
	Firmware Version	Software Version			
1.0.2	1.0.2	1.0.0	2016.05.09	(go)	3058-99M00-100

NOTES: The iControl compatibilities shown below are officially supported by Miranda. Earlier versions may also work, with bugs or limited features.

The Reference number (Ref#) given for each feature or bug in these Release Notes refers to internal Miranda documentation.

UPGRADE PACKAGE: **1.0.2**

Release date: 2016-05-09

iControl compatibility: 5.00 (build 17)

iControl Solo compatibility: 6.0

RCP-200 compatibility: NA

Custom software compatibility: NA

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

ENHANCEMENTS & NEW FEATURES

Ref#	Description
-	

BUGS FIXED IN THIS RELEASE

Ref #	Description
HDALC-13	HDA3941/1941 AND HDA3951/1951 ALARM STATUS ERRORS False information "Signal detected" due to a DVB-S2 option on a nearby IRD-3811.
HDALC-14	THE RECLOCKER ON/OFF INFORMATION IS NOT TRANSMITTED BETWEEN DIFFERENT APPSERVERS.

KNOWN BUGS & LIMITATIONS

Ref #	Description