

8921ADT

4-CH AUDIO A-D CONVERTER WITH DELAY

Release Notes

SOFTWARE VERSION 1.0.0

071827800
OCTOBER 2003

the most watched worldwide

Contacting Grass Valley

| Region | Voice | Fax | Address | Web Site |
|---------------------------------|--|--|---|----------------------------|
| North America | (800) 547-8949 Support: 530-478-4148 | Sales: (530) 478-3347 Support: (530) 478-3181 | Grass Valley P.O. Box 599000 Nevada City, CA 95959-7900 USA | www.thomsongrassvalley.com |
| Pacific Operations | +852-2585-6688 Support: 852-2585-6579 | +852-2802-2996 | | |
| U.K., Europe, Asia, Middle East | +44 1753 218 777 | +44 1753 218 757 | | |
| France | +33 1 45 29 73 00 | | | |
| Germany | +49 221 1791 234 | +49 221 1791 235 | | |

Copyright © Thomson Broadcast and Media Solutions All rights reserved.

Grass Valley Web Site

The www.thomsongrassvalley.com web site offers the following:

Online User Documentation — Current versions of product catalogs, brochures, data sheets, ordering guides, planning guides, manuals, and release notes in .pdf format can be downloaded.

FAQ Database — Solutions to problems and troubleshooting efforts can be found by searching our Frequently Asked Questions (FAQ) database.

Software Downloads — Software updates, drivers, and patches can be downloaded.

8921ADT Release Notes

Introduction

This document provides information on the latest release of the software for use with the 8921ADT module. Read this document completely before attempting to download the latest software.

Pertinent reference documents are available on-line or hard copies can be ordered from Grass Valley Customer Service.

This document details:

- Summary of software release features, and
- Instructions for acquiring and updating software.

Version 1.0.0 Software Release

Refer to the *Important Notes* section below for the 8921ADT v1.0 software release.

Important Notes

Important notes concerning any known software and operating issues in this initial release have been included in [Table 1](#).

Table 1. Known Software and Operating Issues

| Area | Issue |
|--------------|--|
| Sample Rates | User selection between 48 kHz and 96 kHz audio sample rates is not available in this first release. The module will default to 48 kHz. |
| Status Bits | Status bits are not selectable and are set to default values (Professional mode, Audio, and inhibited) for this release. |

System Requirements

For remote control and monitoring capability, the module must be installed in a Gecko 8900TFN-A audio frame equipped with an 8900NET module. Gecko 8900TX-A frames must be upgraded to a TFN version (with fans) to utilize the 8900NET module. For more information on Gecko 8900 frames and the 8900NET module refer to the following reference documents:

- 8900NET Network Interface Instruction Manual
- 8900 Frames Instruction Manual

Software Updating

Any future software update files can be obtained from the Grass Valley ftp site as directed on the Grass Valley Support web page. Refer to [Contacting Grass Valley](#) at the front of this document.

Software update to the module requires an 8900NET module in the frame. The module can be updated using the 8921ADT Software Update web page with the procedure described in the 8900NET Network Interface module available on-line.

You may also use the NetConfig application if available to update the software on the module as described in the NetConfig Instruction Manual.

Accessing Reference Documents

For on-line access to any of the reference documents referred to in these Release Notes, navigate to the following URL:

`http://www.thomsongrassvalley.com/docs`

Select the **Modular Products** link and scroll through the available documents. All of the documents referred to may also be ordered in hard copy from any Grass Valley Sales or Customer Service source. Refer to [Contacting Grass Valley](#) at the front of this document.